RTCA, Inc.
1828 L Street, NW, Suite 805
Washington, DC 20036-5133 USA

Environmental Conditions and Test Procedures for Airborne Equipment

Change 3

RTCA DO-160D Change 3
January 5, 2002

Prepared by: SC-135
© 2002 RTCA, Inc.

Copies of this document may be obtained from

RTCA, Inc.

Telephone: 202-833-9339
Facsimile: 202-833-9434
Internet: www.rtca.org

Please visit the RTCA Online Store for document pricing and ordering information.

Change Transmittal

This change forwards revised text for Section 22.0 – Lightning Induced Transient Susceptibility and Appendix C – Change Coordinators.

- Remove Section 22.0 (dated July 29, 1997) from RTCA/DO-160D and replace with revised Section 22.0.

- Remove Appendix C (dated December 14, 2000) from RTCA/DO-160D and replace with the revised Appendix C.